DACUM Research Chart for Welder

Produced for



DACUM Panel

Troi L. Croswell, Welding Supervisor/Instructor Tecnico Corporation Chesapeake, VA

Marty Dixon, Structural Nuclear Shop Manager Norfolk Naval Shipyard Portsmouth, VA

Michael A. Gillenwaters, Welder Specialist/Production Supervisor Oceaneering International Chesapeake, VA

Christopher Robertson, Welder Specialist/Assistant Resource Manager Oceaneering International Chesapeake, VA

Charlie Spear, President Chesapeake Machine Works Inc. Chesapeake, VA

Joseph Tatum Jr., Crew Leader/Welder BAE Systems Ship Repair Norfolk, VA

Ashley Wilber, Craft Supervisor/Apprentice Instructor BAE Systems Ship Repair Norfolk, VA

John Williamson, NDT Examiner/Weld Program Manager

Produced by



COLLEGE OF EDUCATION AND HUMAN ECOLOGY

DACUM Facilitators

Chesapeake, VA

AMSEC LLC

DACUM International Training Center

Columbus, OH

LaVerne Ellerbe Renee Felts Angela Lawhorne John Moser, Team Leader

April 16-17, 2015

DACUM Research Chart for Welder

DUTIES	TASKS			
A. Complete Welding Certification & Training Requirements	A.1 Complete pre- employment physical	A.2 Obtain security clearance	A.3 Participate in HR training (e.g., ethics, sexual harassment)	A.4 Participate in safety training (e.g., OSHA, maritime)
	A.10 Complete quarterly updates for welding certifications			
B. Obtain Welding Certifications	B.1 Identify certification process (e.g., SMAW, GTAW)	B.2 Identify weldment type (e.g., pipe, plate)	B.3 Identify welding position (e.g., 6G, overhead, vertical, horizontal)	B.4 Weld test assemblies for inspection
C. Perform Shielded Metal Arc Welding (SMAW) Process (Stick)	C.1 Verify SMAW certification	C.2 Participate in SMAW pre-job briefing	C.3 Select SMAW data sheet	C.4 Perform SMAW job site inspection
	C.10 Verify SMAW hot work area is safe for departure	C.11 Remove SMAW equipment from job site		
D. Perform Gas Tungsten Arc Welding (GTAW) Process (TIG)	D.1 Verify GTAW certification	D.2 Participate in GTAW pre-job briefing	D.3 Select GTAW data sheet	D.4 Perform GTAW job site inspection
	D.10 Verify GTAW hot work area is safe for departure	D.11 Remove GTAW equipment from job site		
E. Perform Gas Metal Arc Welding (GMAW) Process (MIG)	E.1 Verify GMAW certification	E.2 Participate in GMAW pre-job briefing	E.3 Select GMAW data sheet	E.4 Perform GMAW job site inspection
	E.10 Verify GMAW hot work area is safe for departure	E.11 Remove GMAW equipment from job site		

April 16-17, 2015

A.5 Participate in hot work training (e.g. fire watch, filler material control)	A.6 Complete welding workmanship training	A.7 Complete annual welder eye exam	A.8 Qualify to welding industry standards (e.g., AWS, NAVSEA)	A.9 Complete respirator training
C.5 Set up job site for SMAW process	C.6 Set up SMAW equipment (e.g., welding machine, ground clamp)	C.7 Perform covered electrode inspections	C.8 Perform SMAW weldments (e.g., butt, fillet)	C.9 Perform visual inspection of SMAW weldments
D.5 Set up job site for GTAW process	D.6 Set up GTAW equipment (e.g., gas bottle, torch)	D.7 Perform GTAW filler material inspections	D.8 Perform GTAW weldments (e.g., butt, sockets)	D.9 Perform visual inspection of GTAW weldments
E.5 Set up job site for GMAW process	E.6 Set up GMAW equipment (e.g., wire feeder, gas bottle)	E.7 Perform GMAW filler material inspections	E.8 Perform GMAW weldments (e.g., butt, fillet)	E.9 Perform visual inspection of GMAW weldments

DACUM Research Chart for Welder

DUTIES	TASKS			
F. Perform Flux Cored Arc Welding (FCAW) Process	F.1 Verify FCAW certification	F.2 Participate in FCAW pre-job briefing	F.3 Select FCAW data sheet	F.4 Perform FCAW job site inspection
	F.10 Verify FCAW hot work area is safe for departure	F.11 Remove FCAW equipment from job site		
G. Perform Oxygen Fuel Cutting (OFC)	G.1 Participate in OFC training	G.2 Participate in OFC pre-job briefing	G.3 Perform OFC job site inspection	G.4 Set up job site for OFC
H. Perform Plasma Arc Cutting (PAC)	H.1 Participate in PAC training	H.2 Participate in PAC pre-job briefing	H.3 Perform PAC job site inspection	H.4 Set up job site for PAC
I. Perform Air Carbon Arc Gouging (ACAG)	I.1 Participate in ACAG training	I.2 Participate in ACAG pre-job briefing	I.3 Perform ACAG job site inspection	I.4 Set up job site for ACAG

April 16-17, 2015

F.5 Set up job site for FCAW process	F.6 Set up FCAW equipment (e.g., wire feeder, gas bottle)	F.7 Perform FCAW filler material inspections	F.8 Perform FCAW weldments (e.g., butt, fillet)	F.9 Perform visual inspection of FCAW weldments
G.5 Set up OFC equipment (e.g., bottles, hoses)	G.6 Perform OFC operations	G.7 Perform visual inspection of OFC sites	G.8 Verify OFC hot work area is safe for departure	G.9 Remove OFC equipment from job site
H.5 Set up PAC equipment (e.g., machine, air hose)	H.6 Perform PAC operations	H.7 Perform visual inspection of PAC sites	H.8 Verify PAC hot work area is safe for departure	H.9 Remove PAC equipment from job site
I.5 Set up ACAG equipment (e.g., machine, air hose)	I.6 Perform ACAG operations	I.7 Perform visual inspection of ACAG site	I.8 Verify ACAG hot work area is safe for departure	I.9 Remove ACAG equipment from job site

General Knowledge and Skills

Knowledge Workmanship inspections Welding positions (vertical, horizontal, overhead) Equipment set up Filler materials Base metals Job set up Joint design: butt joint weld T-joint weld lap joint weld cross joint weld Welding symbols Pre-heat and interpass temperatures Welding procedures and processes Safety requirements **Basic metallurgy** Basic math Welding techniques (bead placement and sequencing) Welder qualifications Welding terminology

<u>Skills</u>

Eye-hand coordination Leadership Decision making Multitasking Time management Communication Job planning Blueprint/schematic reading Interpersonal Problem solving Weld contour (grinding) Reading comprehension

Acronyms

OSHA	Occupational Safety & Health Administration
AWS	American Welding Society
SMAW	Shielded Metal Arc Welding
GTAW	Gas Tungsten Arc Welding
GMAW	Gas Metal Arc Welding
FCAW	Flux Cored Arc Welding
OFC	Oxygen Fuel Cutting
PAC	Plasma Arc Cutting
ACAG	Air Carbon Arc Gouging
NAVSEA	Naval Sea Command
TIG	Tungsten Inert Gas
HR	Human Resources
PPE	Personal Protective Equipment

Behaviors

Honest Team player Dependable Creative Flexible Trustworthy Safety conscious Professional Motivated Trainable Process oriented Accurate Ethical Knowledgeable Reliable Compliant Consistent Driven Mechanically inclined Adaptive Able to work under pressure Ambidextrous Energetic/stamina

Tools, Equipment, Supplies and Materials

Welding shield Hoses (gas, air) Fire extinguisher PPE Face shield Hard hat Knee pads Leather gloves Steel-toed shoes Safety glasses Ear plugs Long sleeves Head covering Respirator Fire retardant clothing Oxy fuel cutting torch Wire cutters Bottle wrench Plasma arc machine Wire feeder Power cables **Drop lights** Fall protection harness Left-vest (over water welding) Magnetic mirror holder Wire brush Slag hammer Needle gun Grinder Electrode holder Weld machine Weld gauges Flow meters TIG torch Welding lead Welding ground clamp Tungsten Filler material (rods, wire) **Temperature sticks Pvrometer** Machinist files Basic hand tools (wrenches, screwdrivers) Allen wrench Burr motors Tool bag Carbon arc rig Flashlight

Future Trends and Concerns

Competitive pay Trend toward automation/use of robotics Job security (sequestration) Insurance cost to employees Shortage of skilled labor Growing difficulty obtaining security clearances New technology changes (drives skill requirements) Trend toward advanced education Welder proficiency levels Retention of welders